## PR001 04-Aug-11

## **Preliminary Report of Accident**

## U.S. Department of Labor

Mine Safety and Health Administration

<b>(%)</b>
~ ``//

1. Accident Type:	2. Accident Classification				3. Date/Time	3. Date/Time of Accident 4. Date/		eath	5. Fatal Case No
Fatal Injury Powered Haula		Haulage		07/11/201	07/11/2011 07:00 PM		07/11/2011 07:00 PM		
6. Mine Information :									·
a) Mining Company Name			b) Mine Nan	ne	c) Parent of Mining Company Alpha Natural Resources				
Martin County Coal			Voyager#7	7	Alpha Natural Resources				
7. Mine Location : a) City		ity	b) County		c) State 8. Mi		8. Mine ID Number	Mine ID Number:	
Inez			Martin		KY	15-19		9193 NO	
10. Primary Mineral Mined:			11. Number o	,	b) Underground	c) Open P	t/Quarry d) N	fill/Prep Plant	e) Other
BITUMINOUS			Mine Employe	es: 64	61				3
12. Contractor Name:						13. (	nion	14. Contrac	ctor ID Number:
15. Contractor Address:	а	) City			b) County		c) State	d) Z	p Code
16. Number of Contractor En	nployees:	a	) Total	b) Underground	i c) Ope	en Pit/Quarry	d) Mill/Pı	ep Plant	e) Other
						<del>.</del>			·
17. Number of Persons in Mi	ne at Time	of Accider	nt:		18. Number	of Persons Una	counted For:		
a) Mine Employees:	22	b)	Contractor Empl	oyees: 0	a) Mine E	mployees:	0 ы С	ontractor Emp	loyees: 0
19) Location of Accident		П nз	O B4	□ 07 A J	M:_:		- DI4	( <b>:e</b> )	20. Mining Heigh
X 01-Underground	•	_	Open Pit		nce Mining	30-Mill/Pr		er (specify)	Feet Inches
02-Surface at Undergro	una	,	-Dredge Mining	Uo-Ketro	eat Mining	99-Office I	асину		5 0
21. Nonfatal Injuries:		22. Fatal	Injuries:	1					
23. Victim Information:		ŕ	Name		b) Age				
		Ryan K	. Thatcher		26				
c) Regular Job Title:	nerator.		d) Act	ivity at Time of A				X N	line Employee
Supply Motor O <sub>l</sub>	<del>JC</del> ! atUI				Supply Inc	otor Operator			
24. Experience : Years W	eeks Days			Weeks Days	<del></del>	Years We	•		Years Weeks Days
24. Experience: Years W a) Total: 6	eeks Days		Years the mine: 1		at activity (23d)	•	d) with	Contractor	Years Weeks Days
24. Experience : Years W a) Total: 6 25. Autopsy Performed:	eeks Days	b) at Location		•	<del></del>	•	d) with	ne No.:	Years Weeks Days
24. Experience: Years W a) Total: 6	eeks Days			•	<del></del>	•	d) with		Years Weeks Days
24. Experience : Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i	eeks Days 4 0 If Yes, I	Location	the mine: 1	24 0 c	) at activity (23d) e, and status of res	Years We	d) with 26. Mine Telepho (606) y operations):	ne No.: 3) 395-2413	
24. Experience : Years W a) Total: 6 25. Autopsy Performed: NO	reeks Days 4 0 If Yes, I  Include equi  Include equi  Include equi  Include victir  Include victir  Include a belt e	ipment inv 7:00 pm n was loo	volved, the exact keep, the supply mocated at a ventil.  The belt exam	24 0 contains the minuster operator, Relation overcast in inner immediate	e, and status of res yan K. Thatcher, at survey station by started CPR	Years We scue and recovery received fata number 96 a and continue	d) with  26. Mine Telepho (606) y operations): I crushing head inj ong the company resuscitation atte	ne No.: b) 395-2413 uries as a re No. 1-A belt mpts until re	suit of a power conveyor when he
24. Experience : Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive	reeks Days 4 0 If Yes, I  Include equi  Include equi  Include equi  Include victir  Include victir  Include a belt e	ipment inv 7:00 pm n was loo	volved, the exact keep, the supply mocated at a ventil.  The belt exam	24 0 contains the minuster operator, Relation overcast in inner immediate	e, and status of res yan K. Thatcher, at survey station by started CPR	Years We scue and recovery received fata number 96 a and continue	d) with  26. Mine Telepho (606) y operations): I crushing head inj ong the company resuscitation atte	ne No.: b) 395-2413 uries as a re No. 1-A belt mpts until re	suit of a power conveyor when he
24. Experience : Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive	eeks Days  4 0  If Yes, I  Include equi oximately The victir by a belt e e, all resur	ipment inv 7:00 pm m was lo examiner scitation	volved, the exact look, the supply mo cated at a ventil.  The belt exam attempts cease	ocation in the min tor operator, Relation overcast ininer immediate and when param	e, and status of res yan K. Thatcher, at survey station by started CPR edics examined	Years We vicue and recover received fats number 96 a and continue the victim an	d) with  26. Mine Telepho (606) y operations): I crushing head inj ong the company I resuscitation atte I found no life sign	ne No.: i) 395-2413 uries as a re No. 1-A belt mpts until re s.	suit of a power conveyor when he aching the surface.
24. Experience: Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive to the company of the surface. Upon reaching the surface.	deeks Days  4 0  If Yes, I  Include equit  Oximately  The victir by a belt e  e, all result  this notice i  cident.	ipment inv 7:00 pm m was lo examiner scitation	yolved, the exact key, the supply mo cated at a ventil. The belt exan attempts cease	ocation in the min tor operator, Relation overcast ininer immediate and when param	e, and status of res yan K. Thatcher, at survey station by started CPR edics examined	Years We vicue and recover received fats number 96 a and continue the victim an	d) with  26. Mine Telepho (606)  y operations): I crushing head inj ong the company resuscitation atte I found no life sign	ne No.: i) 395-2413 uries as a re No. 1-A belt mpts until re s.	suit of a power conveyor when he aching the surface.
24. Experience: Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive to the company of the surface.  The information provided in regarding the cause of the accident and the course of the course of the accident and the course of the course of the course of the accident and the course of the course of the accident and the course of the c	deeks Days 4 0 If Yes, I Include equi oximately The victir by a belt e e, all resur this notice i cident.	ipment inv 7:00 pm m was lo examiner scitation	yolved, the exact key, the supply mo cated at a ventil. The belt exan attempts cease	cation in the minitor operator, Relation overcast miner immediated when parameted	e, and status of res yan K. Thatcher, at survey station by started CPR edics examined	Years We vicue and recover received fats number 96 a and continue the victim an	d) with  26. Mine Telepho (606) y operations): I crushing head inj ong the company I resuscitation atte I found no life sign  regarding the nature	ne No.: 395-2413 uries as a re No. 1-A belt mpts until re s.	suit of a power conveyor when he aching the surface.
24. Experience: Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive Upon reaching the surface The information provided in regarding the cause of the acc 28. Equipment Manufacturer 30. District:	deeks Days 4 0 If Yes, I Include equi oximately The victir by a belt e e, all resur this notice i cident.	ipment inv 7:00 pm m was lo examiner scitation	volved, the exact k to, the supply mo cated at a ventil The belt exan attempts cease	ocation in the min tor operator, R lation overcast niner immediate d when param	e, and status of res yan K. Thatcher, at survey station by started CPR edics examined	Years We vicue and recover received fats number 96 a and continue the victim an	d) with  26. Mine Telepho (606) y operations): I crushing head inj ong the company I resuscitation atte I found no life sign  regarding the nature	uries as a re No. 1-A belt mpts until re s.  c of the inciden C-15UP nt Number: 4199	suit of a power conveyor when he aching the surface.
24. Experience: Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive to the control of t	deeks Days 4 0 If Yes, I Include equi oximately The victir by a belt e e, all resur this notice i cident.	ipment inv 7:00 pm m was lo examiner scitation	volved, the exact k to, the supply mo cated at a ventil The belt exan attempts cease	ocation in the minimum tor operator, Ryation overcast ininer immediated when parameters when parameters and does of the control of the contro	e, and status of resyan K. Thatcher, at survey station ely started CPR edics examined	Years We vicue and recover received fats number 96 a and continue the victim an	d) with  26. Mine Telepho (606) y operations): I crushing head inj ong the company I resuscitation atte I found no life sign  regarding the nature	uries as a re No. 1-A belt mpts until re s. cof the inciden C-15UP nt Number: 4199	suit of a power conveyor when he aching the surface.
24. Experience: Years W a) Total: 6 25. Autopsy Performed: NO 27. Description of Accident (i On July 11, 2011, at apprhaulage related accident. was found unresponsive to Upon reaching the surface Upon reaching the surface The information provided in regarding the cause of the acc 28. Equipment Manufacturer 30. District: C0600 Piket 34. Accident Investigator: Kenneth Fleming 36. Type of Report:	deeks Days 4 0 If Yes, I Include equi oximately The victir by a belt e e, all resur this notice i cident.	ipment inv 7:00 pm n was lo examiner scitation	volved, the exact k to, the supply mo cated at a ventil The belt exan attempts cease	ocation in the minimum of the control operator, Ryation overcast in the immediate of when parameters when parameters and the control of the c	e, and status of resyan K. Thatcher, at survey station by started CPR edics examined not represent final not represent final survey.	Years We vicue and recover received fats number 96 a and continue the victim an	d) with  26. Mine Telepho (606  y operations): I crushing head inj ong the company I resuscitation atte I found no life sign  regarding the nature	uries as a re No. 1-A belt mpts until re s. cof the inciden C-15UP nt Number: 4199	suit of a power conveyor when he aching the surface.  t or conclusions  255  Time 07:15 P

Amended to show correct years of experience